Connector Diagram- RHF Indicator (X20)

Connector Designation	Male/Female	View
X20	**Female**	

Pin Arrangement



Pin Number	Wire Colour	Connects To	Via Connector	Description
1	Black	VMS		0 VDC
2	Blue	VMS		RHF Indicator