
Connector Diagram- LHR Indicator (X24)



Pin Number	Wire Colour	Connects To	Via Connector	Description
1	Black	VMS	X4	0 VDC
2	Blue	VMS	X4	LHR Indicator