


Connector Diagram- VMS (P2)



Pin Number	Wire Colour	Connects To	Via Connector	Description
1	Blue	Display/Speedo		CAN L
2	Green	Display/Speedo		CAN H
3	Orange	Display/Speedo		+12 VDC
4	Blue	RHF Indicator		RHF Indicator
5	Blue	LHF Indicator		LHF Indicator
6	Black	LHF Indicator		0 VDC
7	Brown	Display/Speedo/RHF Indicator		0 VDC
8				
9				
10	Black	Kick Stand Switch		0 VDC
11	Blue	Kick Stand Switch		Kick Stand Switch Signal
12	Red	Kick Stand Switch		+3.3 VDC