


# Connector Diagram- Kill Switch/Throttle (X6)



Pin Number	Wire Colour	Connects To	Via Connector	Description
1	Orange	VMS		+5 VDC
2	White	VMS		Kill Switch
3	Brown	VMS		Kill Switch In
4	Green	VMS		Throttle Signal
5	Black	VMS		0 VDC