
## Connector Diagram- LHF Indicator (X19)



Pin Number	<b>Wire Colour</b>	Connects To	<b>Via Connector</b>	Description
1	Black	VMS		0 VDC
2	Blue	VMS		LHF Indicator