


# Connector Diagram- Speedo/Display (X25)



Pin Number	Wire Colour	Connects To	Via Connector	Description
1				
2				
3				
4				
5				
6				
7	Brown	VMS		0 VDC
8	Orange	VMS		+12 VDC
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19	Green	VMS		CAN H
20	Blue	VMS		CAN L